



# Thermo-Sensor

## S 90

**Pt 100 thermoresistance  
+bimetallic thermometer**

- Simple, fast replacement of any thermoelectric probe
- 1 measurement point, 2 independent systems :  
Pt 100 sensor and bimetallic thermometer
- Use in hazardous areas - option EEx(i)
- Versions according to EN 50020 and EN 50014
- Either one or two Pt 100 sensors can be fitted,  
with or without transmitter



## S 91

**Pt 100 thermoresistance  
+ gas thermometer**

